


Stairway access cover, hatch, and vent to be removed to allow for 12' wide platform, drainage and lighting improvements.



The image shows a dark, narrow, and heavily rusted metal staircase or access point within a larger structure. The walls and ceiling are made of corrugated metal, showing significant rust and wear. A vertical metal rod or pipe runs down the center of the structure. The floor is also made of metal and is covered in rust. The overall appearance is one of age and decay.

Stairway access to be filled in





Tunnel under railroad  
tracks to remain



Network time is not synchronized

Manhole access to main  
tunnel to remain







Manhole access to  
tunnel to remain